

Cargo Pump's Impeller/Shaft Recondition

During Inspection



Shaft wear to frictions area



Impeller wear



Shaft after rebuilding to frictions area with stainless steel electrode

SERVING GREEK
SHIPPING
SINCE 1970

P.P. Liakos

General Ships' Repairs



Shaft final Machining



Ready for Packing



Impeller machining for fitting new Bronze Rings



Impellers/Shaft on standard measurements during dynamic balancing



After fitting and securing new bronze Rings



10, Dervenakion Str., 185 45 Piraeus - Greece
Tel.: +30 210 4630.126 (24hrs) /823 • Fax.: +30 210 4619.583
E-mail: liakos@otenet.gr
www.liakosrepairs.eu